## Replacement Sheet





Fig. 1






Fig. 3A




Fig. 3B




Fig. 4B




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9A




Fig. 9B




Fig.  $10 \triangle$ 




Fig. 10B




Fig.11

.




Fig. 12A




Fig.12 $\mathbb B$ 




Fig.13





Fig. 14A Fig.14B



layout diagram of merchenical arms sensors (47 points)

Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19A

Fig. 19B




Fig. 20




Fig. 21




Fig. 22




Fig. 23





Fig. 24△






Fig.  $25 \triangle$ 




Fig.25B





Fig 26 $\triangle$ 



. Fig. 26B




Fig. 27




Fig. 28

